


**HERITAGE-WTI, Inc.**

1250 St. George Street  
East Liverpool, Ohio 43920-3400  
Phone: 330-385-7337  
Fax: 330-385-7813  
Web Site: www.heritage-wti.com

ISO 9001



ISO 14001

July 14, 2010  
VIA UPS

Mr. George Czerniak, Chief  
U.S. EPA Region V  
Air Enforcement and Compliance Assurance  
Branch  
Mail Code AE-17J  
77 West Jackson  
Chicago, IL 60604

Ms. Pamela Korenewych  
OEPA-DAPC-NEDO  
Environmental Specialist  
2110 E. Aurora Road  
Twinsburg, OH 44087

RE: HERITAGE-WTI, INC.  
EXCESSIVE EXCEEDANCE REPORTING

Dear Mr. Czerniak:

Please find enclosed a written report entitled MACT Excessive Exceedance Report for Heritage-WTI, Inc. This report is required by 40 CFR 63.1206 (c)(3)(vi) whenever there is more than ten emission standard or operating parameter exceedances that occur within a sixty-day period.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are certain penalties for submitting false information including the possibility of fine and imprisonment for knowing violations.

Thank you and if you have any questions or comments, please call me at the above number.

Sincerely,

A handwritten signature in dark ink, appearing to read 'John Peterka', is written over a horizontal line.

John Peterka  
President  
Heritage-WTI, Inc.

cc: Ed Fasco, Ohio EPA-DAPC-NEDO



Recycled Paper

# **MACT EXCESSIVE EXCEEDANCE REPORT**

**Heritage-WTI, Inc**

**July 14, 2010**

## Events

#	Name	Start Time	End Time	Cause (report)	Cause Description	Corrective Actions	(hr)	(min)	(sec)
1	THC	6/12/2010 10:37:28 AM	6/12/2010 10:46:29 AM	Operator Error- Feed Prep	Improper feed prep caused poor combustion	Restarted unit. Review feed instructions.	0	9	1
2	THC	6/14/2010 9:08:24 PM	6/14/2010 10:08:24 PM	Operator Error- Feed Prep	Improper feed prep caused poor combustion	Restarted unit. Review feed instructions.	1	0	0
3	THC	6/16/2010 12:29:24 AM	6/16/2010 1:31:22 AM	Operator Error - Poor Operation	Operator failed to take necessary measures to prevent THC.	Corrected problem. Restarted unit.	1	1	58
4	THC	6/17/2010 9:34:25 PM	6/17/2010 10:34:23 PM	Operator Error- Feed Prep	Improper feed prep caused poor combustion	Corrected problem. Restarted unit.	0	59	58
5	THC	6/21/2010 4:03:22 PM	6/21/2010 4:06:24 PM	Operator Error- Feed Prep	Improper feed prep caused poor combustion	Corrected problem. Restarted unit.	0	3	2
6	SCC Temperature	6/30/2010 3:19:26 PM	6/30/2010 3:29:24 PM	Operator Error - Poor Operation	Operator failed to adjust to temperature loss.	Regained temp. Restarted unit.	0	9	58
7	THC	7/8/2010 1:34:22 AM	7/8/2010 2:19:21 AM	Operator Error - Feed Prep	Improper feed prep caused poor combustion	reduce charge size. Restart unit.	0	44	59
8	SCC Pressure Using Seals	7/9/2010 12:58:49 PM	7/9/2010 12:58:53 PM	Operator Error - Feed Prep	Improper feed prep caused poor combustion	Restarted unit. Reduced charge size.	0	0	4
8	SCC Pressure Using Seals	7/9/2010 12:58:57 PM	7/9/2010 12:59:01 PM	Operator Error - Feed Prep	Improper feed prep caused poor combustion	Restarted unit. Reduced charge size.	0	0	4
9	SCC Pressure Using Seals	7/10/2010 8:42:11 PM	7/10/2010 8:42:18 PM	Operator Error - Feed Prep	Improper feed prep caused poor combustion	Restarted unit. Prep altered.	0	0	7
10	THC	7/13/2010 9:22:23 PM	7/13/2010 10:24:22 PM	Operator Error - Feed Prep	Improperly packaged material caused poor combustion.	Restarted unit. Reduced charge size.	1	1	59

\*\* End of report \*\*

bcc: Env. Dept  
Frank Murray  
Bob Buchheit  
Kevin Lloyd

file name: environ/MACT/HWC MACT/exceedances/eer10\_0714